



(10) COURSES W/ CHECKER WALL OF BRICK ARE LINED WITH THE MARKINGS FROM UNDERNEATH SRU BY MECHANICAL WHERE SKIN REPAIRS ARE TO BE MADE.


069E-201 (#1 SRU) WASTE HEAT RECLAIMER
VIEWING NORTH SIDE VIEW



BURNER WALL
VIEWING WEST



CHECKER WALL



CATFISH MOUTH WALL
VIEWING EAST

WARNING
 IT IS POSSIBLE TO COME IN CONTACT WITH HAZARDOUS MATERIAL IN THIS WORK AREA - REFER TO THE CONTROL UNIT FOR HEALTH SAFETY DATA SHEET FOR ADDITIONAL INFORMATION PRIOR TO STARTING WORK. BY NO MEANS START WORK WITHOUT PROPER INFORMATION AND / OR PROTECTIVE EQUIPMENT. IT IS THE RESPONSIBILITY OF THE CONTRACTOR, COMPANY AND ALL OTHERS TO BE FULLY INFORMED, TRAINED, REVIEWED AND UPDATED CONCERNING ALL HAZARDOUS MATERIALS IN THE WORK AREA. IF IN DOUBT, INQUIRY MUST BE MADE BEFORE STARTING WORK.

SAFETY DIRECTOR: COLT ANDERSON



JOB TITLE:
#1 SRU BRICK REPAIR IDENTIFY

EQUIPMENT ID: 069E-201	UNIT: EXCHANGER
DWG No. RCS-0120735-SRU1	PROJECT: BSR-PWTA 2020
DRAWN BY: H. WHATLEY	DATE: 01/26/2020
REVISD BY: N/A	DATE: -
CHECKED BY: M. WHATLEY	DATE: 01/26/2020
APPROVED BY: M. WHATLEY	DATE: 01/26/2020
SCALE: N/A	REV: A
SIZE: D - 11x17	SHEET: 1 OF 1